

Software Release Notes

1/13/2015

Emotion – Software update

WES7 v1.0.4

Graphics Engine 1.0.0.92

Fixture Firmware 2.0.0.U

Fix:

Issues were encountered with gobo rotation and transition data smoothing, this has been fixed and general improvements have been made. Rotations and transitions across a collaged output have been greatly improved.

Fix:

The synchronization algorithm has been modified to better fit with visual smoothing. Less synchronization packets are needed and playback of synchronized files is better. A DHCP server is required for multiple units to be used in a synchronized group.

Known Issues:

CITP connections to consoles are not processing properly, this is being investigated and an update will be released when available

AVI file with RLE compression should not be used; the movie will only display the first frame of the video file.

MOV's with ProResHD should not be used; the movie will only display the first frame of the video file.

TIPS:

At all times, it is strongly advised to use supplied media encoding template. (MPEG 2, all I-frame) Other formats can be used but synchronization is not supported. Many hard to track problems are directly related to custom content not conforming to the MPEG 2 compression template. If a fixture becomes non-responsive after uploading custom content, please use the "Remove User Media" function on the system restore USB stick.